

IntelliCom Security Bulletin - ISFR-4404-0008- Information

Default passwords in NetBiter firmware images

Release date

January 11, 2010

Last updated:

January 12, 2010

Platform/Product:

NetBiter products

Summary

Downloadable firmware images for the different NetBiter products contain an unencrypted default password for the HICP application. The HICP application is responsible for answering request from the NetBiterConfig utility. This password is the same default password that is mentioned in the product documentation. The password is located in a part of the firmware image that is a writable filesystem and can easily be changed using the NetBiterConfig utility when configuring the product after firmware download.

Recommendation / Solution

We recommend all customers to change this default password by setting a new password using the NetBiterConfig utility.

Known Issues

None

Affected Software

Firmware files for all NetBiter products.